

TEST REPORT IEC 60950-1 Safety of information technology equipment Part 1-General requirements	
Report reference No	R2BJ161101051-03A1
Compiled by (+ signature)	Stone Liang <i>Stone Liang</i>
Approved by (+ signature)	Suky Zhao <i>Suky Zhao</i>
Date of issue	2016-11-02
Testing laboratory	Bay Area Compliance Laboratories Corp. (Dongguan)
Address	No.69,Pulongcun, Puxinhu Industrial Zone, Tangxia Town Dongguan, Guangdong 523719, CHINA
Testing location	As above
Applicant's name	BEIJING EPSOLAR TECHNOLOGY CO., LTD.
Address	NO.228, BLOCK A, 2ND FLOOR, BLDG 1, NO. 3 STREET, SHANGDI XINXI CHANYE JIDI,HAIDIAN DISTRICT, BEIJING,CHINA
Manufacturer's name.....	Same as applicant
Address	Same as applicant
Factory's name.....	BEIJING EPSOLAR TECHNOLOGY CO., LTD.SHENZHEN BRANCH
Address	BLDG.A3, NO.18, FOUTH INDUSTRIAL PARK, ZHULONGTIAN ROAD, SHUITIAN COMMUNITY, SHIYAN STREET, BAOAN DISTRICT, SHENZHEN, GUANDONG PROVINCE, CHINA, 518108.
Standard	IEC 60950-1:2005 (Second Edition) + A1: 2009 + A2: 2013
Test sample(s) received	2016-09-12
Test in period.....	2016-09-12 to 2016-09-20
Procedure deviation	N/A
Non-standard test method	N/A
Note: The test data was only valid for the test sample(s). This test report is prepared for the customer shown above and for the specific product described herein. It must not be duplicated or used in part without prior written consent from Bay Area Compliance Laboratories Corp. (Dongguan).	